Approved For Release 2002/10/46 RDP63-00513A000500120003-1

25	V	1	Δ
25	·Λ	1	А

	3345-63
Copy	5

30 September 1963

MEMORANDUM FOR: Deputy Director (Science and Technology)

SUBJECT

: Daily Activity Report - 30 September 1963

1. Mission Status

25X1

flown on 29 September; estimate 60% successful. Mission 3227 (Sino-Indian Border) was flown on 28 September and was estimated to be 100% successful.

25X1A 25X1A The detachments at ______ are presently on standby as is the one at ______ (Edwards Air Force Base).

- b. BRASS KNOB Four missions were flown 3732 on 27 September, 75% successful with no reaction; 3733 on 27 September, 40% successful and no reaction; 3734 on 28 September, 75% successful with no reaction and 3735 on 29 September, 60 % successful with no reaction.
- c. CORONA CORONA/J mission 1002-2 was reported normal on Revolution 95.

2. OXCART Status:

- Aircrafts 121, 124, 125 and 126, undergoing routine maintenance; #124 was flown for 1:23 hours on a training flight. Next flights are scheduled for 1 October.
- b. Aircraft #122 is undergoing routine maintenance and a remote gear box replacement.
- c. Aircrafts 127 and 128 are undergoing pre-flight inspections. Next flight depends on availability of metal fins.

25X1A

Approved—For Release 2002/10 4 - RDP63-0-313A000500120003-1

25X1A		3345-63

- 3. OXCART Status; 28 September 1963
- a. No flight activity was scheduled for Saturday, 28 September, due to renway overrun repair and routine maintenance of aircrafts.

